

QTY	PART NO.	DESCRIPTION	AMT PARTS
		Replaced R H Rear fender on a Ford 9000	
1	50-245		455.00
4	Robert 1X11 + nuts		80.00
1	Pin B		31.00
8	7/8 thick washers		8.00
1	Roll pin		15.00
		Rollers	350.00
			939.00

Paul By
W. A. R.

H. Bullee & Sons Spring Service Ltd.

1505 FREDERICK STREET Phone 728-0634
BRANDON, MANITOBA R7A 6Z6

Name Robert McBurnie
Address Robert McBurnie, m.B.

2023, 2020

DESCRIPTION OF WORK

AMOUNT

All estimates are for labour only. Materials additional. This company does not assume any responsibility whatever for units left for repairs, storage or other purposes, or for articles left in units. Units driven by our employees at owner's risk.

SUBTOTAL	939.00
P.S.T.	65.73
G.S.T.	46.95
TOTAL	1051.68

622243

GST # R102 305 737